


BP's GOLDEN RULES OF SAFETY

SVT Site Standards incorporates the 8 Golden Rules of Safety. You must be familiar with and comply with these 8 Rules, which are listed below. The detailed rules are available from your Line Manager.



PERSONAL PROTECTIVE EQUIPMENT (PPE)




Full PPE (i.e. Hardhat, zipped-up flame-retardent overalls, safety glasses, safety footwear and appropriate gloves) must be worn outdoors at all times unless in a blue line zone or travelling between blue line zones in a vehicle. Within a blue line zone the minimum PPE requirement is safety glasses. Safety glasses need not be worn in vehicles unless windows are open.

A map indicating the blue line zones is on display at Security.

- Additional requirements for working indoors and outdoors within blue line zones

Safety glasses, safety footwear, zipped-up flame-retardent overalls

- and **appropriate gloves**: in workshops, and for maintenance / construction work.
- **Hard hats** must also be worn inside: for construction work, lifting operations and where risk assessment dictates.
- **Goggles, ear defenders** or respiratory protective equipment must be worn in mandatory areas, and where risk assessment dictates.
- **Disposable or ershoes** must be worn over dirty safety footwear when entering areas displaying the appropriate signage e.g. Maim Administration Building, ESB.
- **Hair** must be worn in such a way that it does not present an entanglement hazard.





Take five

Engage the Brain **BEFORE** the Hands

- 1 Stop, Step Back, Observe
- 2 Think - Through Task
- 3 Identify Hazards
- 4 Control Hazards & Communicate
- 5 Safely Complete Task

Thought **BEFORE** Action





Work Task Health, Safety and Environment Check

